

### PDA

# Staking-tool to remove hands


Datasheet, 01.06.2023, V1.1

Engineered and made in Switzerland

This Staking-tool allows to remove hands without support on the dial.

# The components and their functions

- Pusher
  - Applies the counter-axis on the hand axis
- Knurling-roller
  - o Adjust the working height and remove the hand
- Clamp lever
  - Blocks the counter-axis
- Teflon table
  - Sliding area where comes the movement-holder



### Technical specifications

Weight: 1,2 k

Dimensions (l/d/h): 110 x 120 x 140 mm



#### Tooling needed

Interchangeable parts composed of a counter-axis and a fork made according to your needs.

- Counter shaft
  - Shaft holding the hand axis during the remove
- Fork
  - Housing under the hand



#### Universal movement-holder

Allows a universal tightening of the movement.

The universal movement holder can be purchased separately and used for several applications.

