

Leak testing machines & watchmakers tools

# Plarox PR1 & PR3

# Heating plate

Datasheet, 03.04.2023, V1.1

Engineered and made in Switzerland

The Plarox PR1 and PR3 are machines used to heat the watches before the condensation test. The electronic controller allows the temperature to be adjusted from 25 to 65 °C evenly over the entire surface.

## Machine functions

- Plate for heating the watches before the condensation test
- Temperature adjustable by electronic regulator
- Uniform temperature over the entire surface



#### **Plarox PR3**



### **Technical specifications**

#### Plarox PR1

Supply voltage : Power : Capacity : Heating temperature \* : Weight : Dimensions (l/d/h) : 110-230 V / 50-60 Hz 300 W Up to 20 watches (1 tray) 25 to 65 °C 4,6 kg 290 x 330 x 70 mm

#### Plarox PR3

110-230 V / 50-60 Hz 900 W Up to 60 watches (3 trays) 25 to 65 °C 23 kg 900 x 355 x 105 mm

\* Provided that the ambient temperature does not exceed 25°C.

Roxer SA

www.roxer.ch info@roxer.ch T : +41 ( 0 ) 32 967 86 86 F : +41 ( 0 ) 32 967 86 87 Rue du Collège 92 CH-2300 La Chaux-de-Fonds